

CITY OF SPRINGFIELD

971

\$129.61

SPRINGFIELD, MO., May 12, 1989

MAY 12 1989

Received from Ryder Truck Rentals

One Hundred & Twenty-Nine and 61/100 Dollars

Flush line 4/20/89

Robert R. Schaefer

**RYDER**  
Miami, Florida

62-20  
311

CHECK NUMBER


920913

ISSUED AT Springfield, Missouri 3059 DATE May 10, 1989

PAY One hundred twenty-nine dollars and 61/100 DOLLARS \$ 129.61

TO  
THE  
ORDER  
OF

NAME City of Springfield  
STREET Sanitary Services Division  
CITY, ST. Room 210, City Hall  
ZIP CODE 830 Boonville

Citibank  Delaware Springfield, MO 65802  
A subsidiary of Citicorp.

VOID AFTER 90 DAYS

RYDER TRUCK RENTAL, INC.

Michael J. [Signature]  
AUTHORIZED SIGNATURE

⑈00920913⑈

⑈031100209⑈

38721954⑈

April 27, 1989

Mr. Jerry Beeler, District Manager  
Ryder Truck Rental, Inc.  
2025 E. Chestnut Expressway, Suite L  
Springfield, MO 65802

Re: Sanitary Sewer Blockage - Ryder Truck Rental  
Maintenance Shop - 2412 E. Chestnut Expressway

Dear Mr. Beeler,

As you are aware, the City of Springfield experienced a sanitary sewer blockage on April 20, 1989, in the line that serves your Maintenance Shop at 2412 E. Chestnut Expressway. The blockage was caused by an accumulation of solids in our sewer line. Also, there was a large amount of oil present.

Personnel from this office met with Mr. Scott Jennings from your Maintenance Shop, to inspect the sumps in the garage area. We found that the sumps were not properly plumbed to prevent solids and oil from entering the sanitary sewer. Mr. Jennings indicated that he would correct the problem immediately, which he did. This is the same problem that we experienced on March 20, 1986 (Please find the enclosed letters).

The ordinances of the City of Springfield provide for the recovery of the costs involved in the abatement of a violation under emergency conditions. By means of a copy of this letter, these costs are being certified to the Director of Finance as true and accurate costs incurred by the City of Springfield. Attached to this letter is a detailed explanation of the costs incurred by the City of Springfield. Payment of these costs should be made to the City of Springfield and sent to:

City of Springfield  
City Hall, Room 210  
830 Boonville  
Springfield, MO 65802

Attention: Mr. Robert R. Schaefer

If you have any questions, please feel free to call at 864-1924.

Yours truly,



Gene Pabst

Water Pollution Control Inspector III  
Surveillance & Enforcement

cc: Mr. Fred Fantauzzi, Director of Finance  
Robert R. Schaefer, P.E., Superintendent of Sanitary Services  
Henry M. Cole, P.E., Sanitary Engineer  
Randy Lyman, Sewer Surveillance & Billing Supervisor  
Chuck Griffin, Sewer Cleaning Supervisor

GP:js

2412 E. CHESTNUT EXP

CITY OF SPRINGFIELD  
INTER-OFFICE MEMORANDUM

ATTENTION OF Robert R. Schaefer

DATE 4-21-89

DEPARTMENT SANITARY SERVICES

The following is the amount of labor, material and equipment involved in flushing line at Ryder Truck Rentals, 2412 E. Chestnut Expressway, Wye Map N-15, MH's 55-S, 55-50, 50-49, 49-1, on 4-20-89:

LABOR

1 Working Leader	2 Hrs. - \$14.37 =	\$ 28.74
1 Operator I	2 Hrs. - \$12.06 =	24.12
		<u>\$ 52.86</u>

MATERIAL

1500 Gallons Water	\$0.0045/Gallon =	\$ 6.75
--------------------	-------------------	---------

EQUIPMENT

6055	2 Hrs. - \$35.00/Hr. =	\$ 70.00
------	------------------------	----------

TOTAL .....		\$129.61
-------------	--	----------

SIGNED .....

Charles Griffin  
Sewer Cleaning Supervisor

2412 E. CHESTNUT EXP.

March 12, 1986

Mr. Jerry Reeler, District Manager  
Ryder Truck Rental, Inc.  
2512 E. Glenstone, Suite 19  
Springfield, MO 65804

Dear Mr. Reeler,

This letter is to confirm our conversation on March 10, 1986 concerning the two sumps in the garage area of your building at Patterson Avenue and Chestnut Expressway. As we explained to you at that time, neither of the two sumps are properly plumbed to prevent solids as well as oil from entering the sanitary sewer. We suggested that a "T" fitting be placed on the outfall line of the sumps with a downward pipe extending into the water a minimum of 6 inches. A cleanout can be placed on the top of the "T".

By making these minor changes it should avert any future problem in the City sanitary sewer. Also, not only will this help to keep sand, dirt, oil, ... etc. out of the sanitary sewer, it will keep any possible gases, that might be present in the sanitary sewer, from venting back into your building.

If you have any questions, please feel free to call at 864-1924.

Yours truly,



Gene Pabat  
Water Pollution Control Inspector III  
Surveillance & Enforcement

GP:jn

cc: Mr. Henry Cole, P.E., Sanitary Engineer

2412 E. CHESTNUT EXP.

May 7, 1986

Mr. Jerry Beeler, District Manager  
Ryder Truck Rental, Inc.  
2512 S. Glenstone, Suite 19  
Springfield, MO 65804

Dear Mr. Beeler,

Personnel from this office checked the two sumps, in the garage area of your building at Patterson Avenue and Chestnut Expressway, to see if the requested improvements, as outlined in my letter dated March 12, 1986, had been completed. It appears that all the necessary work has been finished.

Let me thank you for your quick response in taking care of this matter. If you have any problems or questions in the future, please feel free to call at 864-1924.

Yours truly,



Gene Pabst

Water Pollution Control Inspector III  
Surveillance & Enforcement

GP:js

cc: Mr. Henry Cole, P.E., Sanitary Engineer